



KEEP YOUR VT47 ACCURATE, FAST,
AND READY FOR EVERY VEHICLE.


WHY UPDATE?

Updating the ATEQ VT47 ensures compatibility with the latest TPMS protocols and vehicles, helping technicians avoid communication errors during servicing. Regular updates expand the device's sensor coverage, enabling it to recognize and program new OE and aftermarket sensors as they enter the market. This is especially critical for workshops that handle a wide range of vehicle models, as it **minimizes the risk of incomplete diagnostics or failed relearns**. Updates also improve software stability and may introduce faster workflows, UI enhancements, and expanded OBDII functions. In many cases, **an outdated tool leads to wasted time or unnecessary part replacements**, so staying current directly supports shop efficiency and professionalism. With support for wireless updates and a regularly maintained update schedule, keeping the VT47 current is straightforward and low effort — but high reward. It's a small step that ensures the tool remains a reliable part of any technician's daily process.

AN UPDATED VT47 MEANS NO SURPRISES IN THE BAY!

Quick start guide

Before first use, make sure your tool is fully charged and updated with the latest software and vehicle database.



1



www.ateq-tpms.com/downloads

Download the PC software

2



WebVT_V80010.exe

Unzip and click on the exe. file

3

Welcome to the install shield
Wizard for WebTV

Next >

To install software click "Next"

4



The software you are
installing has not been...

Next >

Accept the warning message

5

Welcome to the serial
emulation port driver installer.

Continue

To install drivers click "continue"

6



Connect tool to PC

7

Name

Name



Name

Name

OK

Register your tool

8



Update your tool